

II

1319(T)/23 ENGLAND - East Coast - Buoy.

Source: Crouch Harbour Authority Notice 10/23

1. The pillar buoy, in position 51° 40′.70N., 0° 59′.50E. is reported off station.
2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1975 - 3750 - 5606_6 - 5607_3