

II

2338(T)/23 NETHERLANDS - Buoyage.

Source: Netherlands Notice 24/180(T)/23

1. New light-buoys have been deployed, until further notice, in the following positions:

<i>Characteristic</i>	<i>Designation</i>	<i>Buoy Type</i>	<i>Position</i>
<i>Q(9)15s</i>	<i>ZINK-WKP</i>	West Cardinal	51° 33'·02N., 3° 25'·86E.
<i>Iso.R.8s</i>	<i>OG 6A</i>	Can	51° 31'·62N., 3° 25'·79E.

2. The following light-buoys have been moved:

<i>Characteristic</i>	<i>Designation</i>	<i>Former Position</i>	<i>New Position</i>
<i>VQ.R</i>	<i>OG 8</i>	51° 31'·26N., 3° 26'·04E.	51° 31'·16N., 3° 26'·21E.
<i>Iso.R.8s</i>	<i>OG 10</i>	51° 30'·47N., 3° 27'·42E.	51° 30'·33N., 3° 27'·72E.

3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

Chart affected - 116 (INT 1477)