

II

2874(P)/16 BELGIUM - Blighbank - Works. Wind farm. Buoyage. Restricted area.

Source: Belgian Notice 9/144(T)/16

1. Works are in progress to extend the Belwind windfarm at Blighbank in position 51° 40'·35N., 2° 48'·40E.
2. The construction area is bounded by the following positions and marked as follows:

<i>Position</i>	<i>Buoy Type</i>	<i>Designation</i>
*51° 38'·66N., 2° 45'·02E.	West cardinal light-buoy	BB-W
51° 39'·75N., 2° 45'·87E.	Special buoy	BB1
51° 40'·84N., 2° 46'·55E.	Special buoy	BB2
51° 41'·93N., 2° 47'·23E.	Special buoy	BB3
51° 43'·03N., 2° 47'·91E.	North Cardinal light-buoy	BB-N
*51° 40'·77N., 2° 51'·05E.	Special buoy	BB4
51° 39'·94N., 2° 52'·68E.	East Cardinal light-buoy	BB-E
51° 39'·03N., 2° 51'·59E.	Special buoy	BB5
51° 38'·12N., 2° 50'·51E.	Special buoy	BB6
51° 37'·21N., 2° 49'·42E.	Special buoy	BB7
51° 36'·30N., 2° 48'·33E.	South Cardinal light-buoy	BB-S
*51° 39'·30N., 2° 46'·46E.	Wave recorder buoy	BB8
*51° 39'·72N., 2° 50'·54E.	Wave recorder buoy	BB9

3. Unauthorised vessels are not permitted to enter the construction area.
4. Mariners are advised to navigate clear of the limits of the construction area.
5. Charts will be updated when works are complete.
6. Former Notice 1324(P)/16 is cancelled.

*Indicates new or revised entry.
(WGS84 Datum)

Charts affected - 1406 - 1630 (INT 1416) - 1872 - 1874 (INT 1474) - 2449