

II

3093(P)/20 BELGIUM - Restricted area. Wind turbines.

Source: Belgian Notices 10/176-178/20

1. Following the completion of the Northwester 2 Wind Farm, a safety zone, entry prohibited, has been established, joining the following positions:

51° 41'·24N., 2° 42'·82E.

51° 42'·51N., 2° 45'·42E.

51° 42'·89N., 2° 47'·67E.

51° 38'·89N., 2° 45'·29E.

51° 39'·13N., 2° 44'·78E.

2. Wind turbines, *Fl(3)Y.15s5M Horn*, have been established in the following positions:

51° 41'·30N., 2° 43'·41E.

51° 41'·97N., 2° 44'·80E.

51° 42'·56N., 2° 46'·91E.

51° 41'·35N., 2° 46'·19E.

51° 39'·50N., 2° 45'·07E.

51° 40'·56N., 2° 44'·04E.

3. Charts 1630 and 8297 will be updated when full details are available.
4. These changes will be included in a New Edition of Chart 1234 to be published mid 2020.
5. Charts 1406 will be updated by Notice to Mariners.
6. Former Notice 3989(P)/19 is cancelled.
(WGS84 DATUM)

Charts affected - 1630 (INT 1416) - 2449 - 8297