

II

3095(T)/23 ENGLAND - East Coast - Buoyage.

Source: Crouch Harbour Authority Notices 35-36/23

1. The following light-buoys are reported to be off station:

<i>Characteristic</i>	<i>Designation</i>	<i>Position</i>
<i>Fl.Y.10s</i>	<i>Swallowtail No 2</i>	51° 40'·84N., 1° 04'·39E.
<i>Fl(2)Y.10s</i>	<i>Swallowtail No 3</i>	51° 40'·52N., 1° 03'·45E.

2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1975 - 3750 - 5606_6 - 5607_3