

II

3810(T)/17 BELGIUM - Blankenberge - Buoyage.

Source: Belgian Notices 14/190(T)-191(T)/17).

1. Shoaling exists at the entrance to Blankenberge.
2. Starboard-hand, lateral light-buoys have been temporarily established in the following positions:

<i>Designation</i>	<i>Characteristic</i>	<i>Position</i>
<i>BL1</i>	<i>Fl(2)G.5s</i>	51° 18'·928N., 3° 06'·372E.
<i>BL3</i>	<i>Q.G</i>	51° 18'·932N., 3° 06'·403E.
<i>BL5</i>	<i>Fl(2)G.5s</i>	51° 18'·938N., 3° 06'·435E.
<i>BL7</i>	<i>Q.G</i>	51° 18'·942N., 3° 06'·469E.
<i>BL9</i>	<i>Q.G</i>	51° 18'·941N., 3° 06'·501E.

3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

Chart affected - 1872