

II

4036(T)/15 NETHERLANDS - Approaches to Vlissingen - Buoyage. Depths.

Source: Netherlands Notices 19/228(T)/15 and 29/322(T)/15

1. Due to dredging operations, the buoyage in the approaches to Vlissingen has changed. The following light-buoys have been moved:

| <i>Light-buoy</i> | <i>Characteristic</i> | <i>New position</i> |
|-------------------|-----------------------|---------------------------|
| <i>OG 14</i> | <i>VQ.R</i> | 51° 27'·23N., 3° 31'·74E. |
| <i>*OG 12</i> | <i>Iso.R.4s</i> | 51° 27'·43N., 3° 31'·88E. |

2. A port-hand lateral buoy, *OG 10A*, has been established in position 51° 27'·81N., 3° 31'·27E.
3. The yellow buoy, *Westduin*, has been removed from position 51° 27'·39N., 3° 31'·69E.
4. Depths exist in the following positions:

| <i>Depth</i> | <i>Position</i> |
|--------------|---------------------------|
| 6·6m | 51° 27'·32N., 3° 31'·48E. |
| 6·2m | 51° 26'·40N., 3° 33'·75E. |

5. Mariners are advised to navigate with caution in the area.
6. Former Notice 3618(T)/15 is cancelled.
* Indicates new or revised entry.
(WGS84 Datum)

Charts affected - 120 (INT 1479) - 1872 - 1874 (INT 1474) - 8011 - 8012