

II

4078(T)/18 NORTH SEA - Netherlands Sector - Buoyage.

Source: Netherlands Notice 31/266(T)/18

1. Light-buoys have been established in the following positions:

| <i>Buoy Type</i> | <i>Designation</i> | <i>Characteristic</i> | <i>Position</i> |
|------------------|--------------------|-----------------------|---------------------------|
| North Cardinal | <i>BB-North</i> | <i>VQ</i> | 51° 43'·65N., 2° 57'·93E. |
| South Cardinal | <i>BB-South</i> | <i>Q(6)+LFl.15s</i> | 51° 43'·54N., 2° 57'·93E. |

2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

Charts affected - 110 (INT 1473) - 1630 (INT 1416)