

II

2400(T)/21 NETHERLANDS - Buoy. Precautionary area.

Source: Netherlands Notice 20/171(T)/21

1. The east cardinal light buoy, *VQ(3)5s SG-W*, has been temporarily moved:

<i>Former Position</i>	<i>New Position</i>
51° 26'·43N., 3° 33'·71E.	51° 26'·30N., 3° 33'·95E.

2. A precautionary area has been temporarily amended:

<i>Former Positions</i>	<i>New Positions</i>
51° 26'·65N., 3° 33'·33E.	51° 26'·65N., 3° 33'·33E.
51° 26'·43N., 3° 33'·71E.	51° 26'·30N., 3° 33'·95E.
51° 25'·85N., 3° 33'·28E.	51° 25'·85N., 3° 33'·28E.

3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

Charts affected - 116 (INT 1477) - 1872 - 1874 (INT 1474)