

## II

### **2588(P)/24 ENGLAND - East Coast - Outfall. Buoyage. Works.**

Source: Southern Water Services

1. Outfall construction works are taking place within an area bounded by the following positions:

51° 21'·97N., 1° 03'·77E.

51° 22'·63N., 1° 03'·82E.

51° 22'·62N., 1° 04'·00E.

51° 22'·23N., 1° 04'·03E.

51° 22'·05N., 1° 03'·97E.

2. The works area is marked by yellow buoys.

3. Mariners are advised to navigate with caution in the area.

4. Charts will be updated when works are complete.

(ETRS89 DATUM)

**Charts affected - 1183 (INT 1561) - 1607 (INT 1562) - 5606\_2 - 5606\_5**