

II

**2977(T)/23 ENGLAND - East Coast - Light-float. Automatic Identification System. Buoy.
Fog signal.**

Source: Trinity House Notice 16/23

1. The Sunk Inner light-float, *Fl(5)15s11m12M, Horn(1)30s, Racon(T), AIS*, in position 51° 51'·17N., 1° 34'·40E. has been temporarily removed. A Safe Water Buoy, *LFl.10s9M, Wave Actuated Bell, Racon(T), AIS* has been temporarily established in its place.
2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1183 (INT 1561) - 1406 - 1408 - 1610 (INT 1511) - 1975 - 2052 (INT 1560) - 2182A (INT 1043) - 2692 - 5607_1 - 5607_2 - 5614_25