

II

4382(T)/21 ENGLAND - East Coast - Light-float. Buoy.

Source: King's Lynn Conservancy Board Notice 28/21

1. The Roaring Middle light-float, *LFl.10s7m8M*, in position 52° 58'·64N., 0° 21'·08E. has been temporarily removed. A safe water buoy, *LFl.10s*, has been established in its place.
2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 108 - 1190 (INT 1508) - 1200 (INT 1556)