

II

598(T)/24 ENGLAND - South Coast - Buoyage.

Source: Dover Harbour Board

1. The yellow light-buoy, *Fl(4)Y.6s, North East*, in position $51^{\circ} 07' \cdot 317N.$, $1^{\circ} 19' \cdot 875E.$ is reported to be off station.
2. The yellow light-buoy, *Fl(5)Y.20s*, in position $51^{\circ} 07' \cdot 355N.$, $1^{\circ} 20' \cdot 684E.$ is reported to be temporarily extinguished.
3. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1698 (INT 1736) - 5605_14