

II

866(T)/23 ENGLAND - East Coast - Buoyage.

Source: Crouch Harbour Authority Notices 4/23 and 8/23

1. The following lateral buoys are reported to be off station:

<i>Characteristic</i>	<i>Designation</i>	<i>Position</i>
<i>Fl.R.10s</i>	<i>Outer Crouch No 4</i>	51° 38'·00 N., 0° 58'·00 E.
<i>Fl(2)R.5s</i>	<i>Whitaker No 4</i>	51° 39'·77N., 1° 03'·43E.

2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1975 - 3750 - 5606_6 - 5607_3