

II

4799(T)/24 ENGLAND - East Coast - Buoy.

Source: Peel Ports London Medway Notice 10/24

1. The mooring buoy in position 51° 25'·470N., 0° 41'·978E. has been replaced by an orange marker buoy until further notice.
2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1185 (INT 1572) - 1834 - 2482 (INT 1573) - 5606_10 - 5606_11