

ADMIRALTY NOTICES TO MARINERS

888(T)/2019 NETHERLANDS - Buoyage.

Source: Netherlands Notice 3/41(T)/19

(SEP: 2019000011916 - 159206).

1. The following buoys have been temporarily removed:

<i>Designation</i>	<i>Position</i>
GR 9	51° 30'·94N., 3° 24'·47E.
DL 1	51° 30'·73N., 3° 24'·49E.
DL 2	51° 30'·76N., 3° 25'·02E.
DL 4	51° 30'·39N., 3° 25'·43E.
DL 6	51° 29'·80N., 3° 26'·63E.
DL 8	51° 29'·19N., 3° 27'·84E.
DL 9	51° 27'·99N., 3° 29'·54E.
DL 10	51° 28'·59N., 3° 29'·06E.

(WGS84 DATUM)

Charts affected - 116 (INT 1477) - 1872 - 1874 (INT 1474)