

II

2027(P)/23 NETHERLANDS - Buoyage.

Source: Netherlands Notice 21/153(P)/23

1. Changes to buoyage have taken place in the vicinity of the following positions:

<i>Location</i>	<i>Position</i>
Banjaard	51° 43'·17N., 3° 32'·69E.
Westgat	51° 38'·96N., 3° 30'·80E.
Roompot	51° 36'·15N., 3° 32'·05E.

2. Buoy-positions have changed, topmarks and lights have been altered.

3. Charts will be updated when full details are available.

4. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

Charts affected - 110 (INT 1473) - 116 (INT 1477) - 1630 (INT 1416) - 1872 - 1874 (INT 1474)