

II

4333(T)/22 NETHERLANDS - Buoyage.

Source: Netherlands Notice 41/289(T)/22

1. The following light-buoys have been moved:

<i>Characteristic</i>	<i>Designation</i>	<i>Former Position</i>	<i>New Position</i>
<i>VQ(3)5s</i>	<i>SG-W</i>	51° 26'·43N., 3° 33'·70E.	51° 26'·34N., 3° 33'·88E.
<i>Iso.G.4s</i>	<i>SG 3</i>	51° 26'·62N., 3° 33'·46E.	51° 26'·72N., 3° 33'·21E.
<i>VQ.R</i>	<i>OG 20</i>	51° 27'·23N., 3° 31'·67E.	51° 27'·30N., 3° 31'·52E.

(WGS84 DATUM)

Charts affected - 116 (INT 1477) - 1872 - 1874 (INT 1474)