

II

5855(T)/24 ENGLAND - East Coast - Buoy.

Source: Port of London Authority

1. The starboard-hand lateral buoy, *Fl.G.5s Mid Swatch*, has been temporarily moved.

Former Position

51° 28'·67N., 0° 44'·15E.

New Position

51° 28'·87N., 0° 43'·32E.

2. Mariners are advised to navigate with caution in the area.
(ETRS89 DATUM)

Charts affected - 1185 (INT 1572) - 3683 - 5606_7 - 5606_8 - 5606_9