

II

2868(T)/18 BELGIUM - Wielingen - Obstruction. Buoy.

Source: Belgian Notice 11/142(T)/18

1. An obstruction, dangerous to surface navigation, exists in position $51^{\circ} 19' \cdot 91\text{N.}, 3^{\circ} 08' \cdot 39\text{E.}$
2. A north cardinal light-buoy, *Q NM*, has been established in position $51^{\circ} 20' \cdot 07\text{N.}, 3^{\circ} 07' \cdot 99\text{E.}$
(WGS84 DATUM)

Charts affected - 1872 - 1874 (INT 1474) - 2449