

ADMIRALTY NOTICES TO MARINERS

~~3068(T)/2016 IRELAND - East Coast - Belfast Lough - Folly Roads NW - Marine farm - Buoyage.~~

~~Source: Belfast Harbour Notices 4/16 and 7/16~~

~~(SEP: 2016000103363 - 1).~~

- ~~1. Two lines of marine aquaculture floats, marked by special buoys, *FL.Y.3s*, have been deployed until September 2016, within an area bounded by the following positions:~~

~~54° 41' 17N., 5° 51' 30W.~~

~~54° 41' 17N., 5° 51' 03W.~~

~~54° 40' 88N., 5° 51' 08W.~~

~~54° 40' 88N., 5° 51' 30W.~~

- ~~2. Mariners are advised to navigate with caution in the area.
(WGS84 Datum)~~

~~Charts affected - 1752 (INT 1664) - 1753 (INT 1661)~~

3082(T)/2016 ENGLAND - East Coast - Sunk Inner Precautionary Area - South Ship Head E - Buoyage. Scientific instruments.

Source: Harwich Haven Authority Notice 12/16

(SEP: 2016000122411 - 1).

1. Scientific instruments have been temporarily established on the seabed. Each site will be marked by a Dan Buoy in the following positions:

<i>Designation</i>	<i>Position</i>
Dan 1	51° 54' 58N., 1° 36' 84E.
Dan 2	51° 53' 86N., 1° 36' 16E.
Dan 3	51° 53' 07N., 1° 35' 53E.
Dan 4	51° 54' 41N., 1° 35' 94E.
Dan 5	51° 53' 65N., 1° 35' 29E.

2. The northern and southern limit of the area will be marked by two yellow light-buoys established in the following positions:

<i>Position</i>	<i>Characteristic</i>
51° 54' 66N., 1° 36' 91E.	Fl(5)Y.20s
51° 53' 00N., 1° 35' 48E.	Fl(5)Y.20s

3. These instruments are expected to remain in position for approximately 4 months.
4. Mariners are requested to give a wide berth.
(ETRS89 Datum)

Charts affected - 1183 (INT 1561) - 2052 (INT 1560) - 2692