

## II

### 477(P)/23 ENGLAND - East Coast - Depths. Drying heights. Light.

Source: Port of Boston Authority

1. Recent survey information has shown that depths and drying heights less than charted exist within the approaches to the Port of Boston. The most significant are as follows:

<i>Depth</i>	<i>Position</i>
5.3m	52° 57'.25N., 0° 07'.86E.
3.5m	52° 57'.15N., 0° 07'.86E.
0.6m	52° 56'.73N., 0° 07'.58E.
0.8m	52° 56'.53N., 0° 07'.16E.
0.3m	52° 56'.19N., 0° 05'.36E.
1.2m	52° 56'.14N., 0° 05'.18E.
<i>Drying height</i>	<i>Position</i>
0.8m	52° 57'.06N., 0° 08'.00E.
0.9m	52° 56'.96N., 0° 07'.81E.
1.9m	52° 56'.88N., 0° 07'.98E.

2. Light characteristics at Tabs Head light in position 52° 56'.01N., 0° 04'.92E. have been amended to Q.4m1M
3. Mariners are advised to navigate with caution in the area.
4. These changes will be included in a New Edition of Charts 1200, 5614\_11 and 5614\_12 to be published early 2023. (ETRS89 DATUM)

**Charts affected - 1200 (INT 1556) - 5614\_11 - 5614\_12**